

Screw Drill Set (with HSCO drills)

KL-0181-21 K

Used to remove broken screws and thread bolts with thread M5 - M16.

Procedure:

1. Open the broken bolt (or screw) by drilling (use boring bush if necessary).
2. Drive in the pin.
3. Place the nut on the pin and extract by means of a screw-wrench.



Sets of Drill-Out Pins

KL-0181-Series

Set of Drill-Out Pins 1/8" (5 units)

KL-0181-2112

Technical Data:

Drill-Ø:	3.2 mm
----------	--------



Set of Drill-Out Pins 3/16" (5 units)

KL-0181-2122

Technical Data:

Drill-Ø:	4.8 mm
----------	--------

Set of Drill-out Pins 5/16"(5 units)

KL-0181-2142

Technical Data:

Drill-Ø:	8.0 mm
----------	--------

Set of Drill-Out Pins 1/4" (5 units)

KL-0181-2132

Technical Data:

Drill-Ø:	6.4 mm
----------	--------

Set of Drill-Out Pins 11/32" (5 units)

KL-0181-2152

Technical Data:

Drill-Ø:	8.0 mm
----------	--------

Frame Micrometer 0-25 mm

KL-0140-40

Features a ratchet stop and clamping-ring, a concealed, hardened, ground, and adjustable spindle with hand guard insulating pads. Measuring range from 0-25 mm; surfaces chrome-plated.

Technical Data:

Range:	0-25 mm
Pitch:	0.5 mm
Weight:	350 g



Frame Micrometer 25-50 mm

KL-0140-41

Features a ratchet stop and clamping-ring, a concealed, hardened, ground, and adjustable spindle with hand guard insulating pads. Measuring range from 25-50 mm; surfaces chrome-plated.

Technical Data:

Range:	25-50 mm
Pitch:	0.5 mm
Weight:	500 g

